

Summary of Facility Information in the County of Phillips

Owner Name and Address: E Bruce Kirkaldie Lodgepole Store Dodson MT 59524 Phone: (406) 673-3255

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|----------------------|-------------------------|---------------|-------|----------------|
| 0306293 | Lodge Pole Store UST | General Delivery | Dodson | 59524 | (406) 673-3255 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|----------------------------------|--------------|----------------------|---------------------|------------------------------------------------|-------------------------------------|-------------|--------------------------------------------------------------------------------|-------------------------|
| 1 / 01 Temporarily Out of Use | | 4/24/1986 20 / No | Gasoline 1,000 | Asphalt Coated or Bare Steel None | Galvanized Steel None | Not Listed | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | No No No No |
| 2 / 02 Temporarily Out of Use | | 4/25/1971 35 / No | Gasoline 2,000 | Asphalt Coated or Bare Steel None | Galvanized Steel None | Not Listed | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | No No No No |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Phillips

Owner Name and Address: Adams Convenience Store Inc 902 S Central Ave PO Box 490 Malta MT 59538 Phone: (406) 654-2268

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------|---------------------------------|---------------|-------|----------------|
| 3602359 | Packys Inc | 902 S Central Ave PO Box 490 | Malta | 59538 | (406) 654-2268 |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction | Piping Material | Piping Type | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|-----------|----------------------------------|--------------------|--------------------------------------|-----------------------------------|----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---|----------------------------------|----------------------------------|---|---|---|---|---|---|----------------------------------|---|---|--|---|--|---|---|----------------------------------|---|---|---|---|----------------------------------|-------------------|
| Status | | | | Secondary Option | Secondary Option | | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 2 / S7 Currently in Use | 892 | 6/1/1994 12 / Ye | Gasoline 17,000 | Asphalt Coated or Bare Steel None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | D | E | F | G | H | I | J | <input checked="" type="radio"/> | L | B | | D | | E | F | G | H | I | J | K | <input checked="" type="radio"/> | No Yes Yes Yes |
| A | B | C | D | E | F | G | H | I | J | <input checked="" type="radio"/> | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | | E | F | G | H | I | J | K | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 3 / S8 Currently in Use | 893 | 6/1/1994 12 / Ye | Gasoline 17,000 | Asphalt Coated or Bare Steel None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | <input checked="" type="radio"/> | D | E | F | G | H | I | J | K | L | B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | No Yes Yes Yes |
| A | B | <input checked="" type="radio"/> | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Phillips

Owner Name and Address: Little Otts Inc 3 N 1st St E PO Box 9 Malta MT 59538 Phone: (406) 654-1199

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------|-------------------------|---------------|-------|----------------|
| 3602371 | Little Otts Inc | 3 N 1st St E | Malta | 59538 | (406) 654-1199 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|-----------------------|--------------------|------------------------------------------------|-------------------------------------|-------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| 2 / 02 Currently In Use | 3287 | 10/29/1986 19 / No | Diesel 6,000 | STI-P3 None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently In Use | 3288 | 10/29/1986 19 / No | Diesel 6,000 | STI-P3 None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently In Use | 3289 | 10/1/1998 07 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently In Use | 3290 | 10/1/1998 07 / No | Gasoline 5,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Phillips

Owner Name and Address: Westside Self Service Inc Highway 2 West PO Box 1770 Malta MT 59538 Phone: (406) 654-2144

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------------|-------------------------|---------------|-------|----------------|
| 3606668 | Westside Self Service Inc | US Highway 2 & Road 242 | Malta | 59538 | (406) 654-2331 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|--------------------|------------------------------------------------|------------------------------------------------|-------------|--------------------------------------------------------------------------------|-------------------------|
| 1 / S1 Currently in Use | 2256 | 7/1/1994 12 / Ye | Gasoline 12,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B ● D E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / S2 Currently in Use | 2257 | 9/2/1996 09 / Ye | Diesel 12,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B ● D E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / S3 Currently in Use | 2258 | 7/1/1994 12 / Ye | Gasoline 12,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B ● D E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / S4 Currently in Use | 2259 | 7/1/1994 12 / Ye | Gasoline 12,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B ● D E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / S5 Currently in Use | 2260 | 8/29/1996 09 / Ye | Diesel 8,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B ● D E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently in Use | 5069 | 4/25/2006 00 / No | Gasoline 15,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C ● E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 7 / 07 Currently in Use | 5070 | 4/25/2006 00 / No | Diesel 15,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C ● E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 8 / 08 Currently in Use | 5071 | 4/25/2006 00 / No | Diesel 15,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C ● E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Phillips

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------------------------|------|----------------------|-------------------|---------------------------------------|------------------------------------------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|--|--|--------------------|
| 9 / 09 Currently in Use | 5075 | 4/25/2006 00 / No | Diesel 5,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table> | A | B | C | ● | E | F | G | H | I | J | K | L | B | ● | E | F | ● | H | I | J | K | L | | | Yes Yes Yes Yes |
| A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | ● | E | F | ● | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |
| 10 / 10 Currently in Use | 5076 | 4/25/2006 00 / No | Diesel 5,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table> | A | B | C | ● | E | F | G | H | I | J | K | L | B | ● | E | F | ● | H | I | J | K | L | | | Yes Yes Yes Yes |
| A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | ● | E | F | ● | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |
| 11 / 11 Currently in Use | 5077 | 4/25/2006 00 / No | Gasoline 5,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table> | A | B | C | ● | E | F | G | H | I | J | K | L | B | ● | E | F | ● | H | I | J | K | L | | | Yes Yes Yes Yes |
| A | B | C | ● | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | ● | E | F | ● | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Phillips

Owner Name and Address: Equity Coop Association PO Box 340 Malta MT 59538 Phone: (406) 654-2240

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------------------|-------------------------|---------------|-------|----------------|
| 3610706 | Equity Coop Association Malta | 428 S 1st St E | Malta | 59538 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|--------------------|------------------------------------------------|------------------------------------------------|-------------|--------------------------------------------------------------------------------|-------------------------|
| 3 / S3 Currently In Use | 860 | 12/9/1994 11 / Ye | Gasoline 25,600 | Unknown None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / S4 Currently In Use | 861 | 12/9/1994 11 / Ye | Diesel 17,000 | Unknown None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / S5 Currently In Use | 862 | 12/9/1994 11 / Ye | Diesel 12,000 | Unknown None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 6 / S6 Currently In Use | 863 | 12/9/1994 11 / Ye | Gasoline 9,900 | Unknown None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Phillips

Owner Name and Address: Ezzies Wholesale Inc PO Box 1770 Malta MT 59538 Phone: (406) 654-2331

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------------|-------------------------|---------------|-------|----------------|
| 3611372 | Ezzies Wholesale US 2 E | US Highway 2 E | Malta | 59538 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|-------------------|------------------------------------------------|---------------------------------------|-------------|----------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| 1 / 01 Currently in Use | 886 | 1/1/1990 16 / No | Diesel 6,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently in Use | 887 | 1/1/1990 16 / No | Diesel 6,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently in Use | 888 | 1/1/1990 16 / No | Diesel 6,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently in Use | 889 | 1/1/1990 16 / No | Gasoline 6,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / 05 Currently in Use | 890 | 1/1/1990 16 / No | Gasoline 6,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently in Use | 891 | 1/1/1990 16 / No | Gasoline 6,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Phillips

Owner Name and Address: Phillips County Medical Center 417 S 4th St E PO Box 640 Malta MT 59538 Phone: (406) 654-1100

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------------------|-------------------------|---------------|-------|----------------|
| 5614104 | Phillips County Medical Center | 417 S 4th St E | Malta | 59538 | (406) 654-1100 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|------------------|------------------------------------------------|------------------------------------------------|-------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| 1 / 01 Currently In Use | 4884 | 3/2/2004 02 / No | Diesel 1,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently In Use | 4885 | 3/2/2004 02 / No | Diesel 1,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Phillips

Owner Name and Address: Farmers Union Oil Co Main Street Whitewater MT 59544 Phone: (406) 674-5515

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------------------|-------------------------|---------------|-------|----------------|
| 3604082 | Farmers Union Oil Co Whitewater | Main St | Whitewater | 59544 | (406) 674-5515 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|-----------------------|--------------------|------------------------------------------------|-------------------------------------|-------------|--------------------------------------------------------------------------------|-------------------------|
| 5 / S5 Currently In Use | 3599 | 10/13/1998 07 / Ye | Diesel 10,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 6 / S6 Currently In Use | 3600 | 10/13/1998 07 / Ye | Gasoline 15,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 7 / S7 Currently In Use | 3601 | 10/13/1998 07 / Ye | Diesel 9,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 8 / S8 Currently In Use | 3602 | 10/13/1998 07 / Ye | Diesel 9,000 | Unknown None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Phillips

Owner Name and Address: Zortman Garage & Motel PO Box 302 Zortman MT 59546 Phone: (406) 673-3160

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|------------------------|-------------------------|---------------|-------|----------------|
| 3611549 | Zortman Garage & Motel | 302 Main St | Zortman | 59546 | (406) 673-3160 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|---------------------|------------------------------------------------|---------------------------------------|--------------|--------------------------------------------------------------------------------|-------------------------|
| 3 / 03 Currently In Use | 4020 | 6/17/1999 07 / No | Gasoline 1,000 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 4 / 04 Currently In Use | 4021 | 6/17/1999 07 / No | Diesel 1,000 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |